


FORM MR-AR
(Revised 3/98)

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/2000 To (mo./yr.) 12/2000
 2. DOGM File Number (Mine No): S / 035/ 17
 3. Mine Name: Little Cottonwood - Granite Extraction
 4. Mineral(s) Mined (or permitted to mine): Granite
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
NW 1/4, SW 1/4, 1/4, Section 8, Township T35, Range R-2E
1/4, 1/4, 1/4, Section , Township , Range
1/4, 1/4, 1/4, Section , Township , Range
 7. Name of Operator or Company: Corp. of Presiding Bishop
 8. Permanent Street Address: 15 East South Temple Street
City, State, Zip: Salt Lake City, Utah 84150-6330
Phone: (801) 240-6448 Fax: (801) 240-1335
 9. Company Representative (or designated operator):
Name: Kerry B. Nielsen, AIA
Title: Project Architect
Business Address: 15 East South Temple Street
City, State, Zip: Salt Lake City, Utah 84150-6330
Phone: (801) 240-6448 Fax: (801) 240-1335
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☐ No ☒
2. If no - what was the last year of activity? 1999
3. If yes - how much ore or mineral was mined? NA

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
Mineral extraction ended Dec. 1999.
The site was reclaimed by regrading rock, stabilization and revegetation, trees, shrubs, and seed.
5. How much additional acreage was disturbed during the past year? 0
6. How much acreage was reclaimed during the past year? 4.5 Acres
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
See #4
Restoration work very successful.
8. What is the total disturbed acreage of entire project at years end? 0
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
None -
Reclamation complete
Signs and perimeter fence will be removed.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Kerry B. Nielsen, AIA

Title of Operator:

Project Architect for Owner

Signature of Operator:

[Signature]

Date:


1-12-2001

THE CHURCH OF
JESUS CHRIST
OF LATTER-DAY SAINTS

SPECIAL PROJECTS DIVISION
Temple Construction Department
Joseph Smith Memorial Building
Eighth Floor
15 East South Temple Street
Salt Lake City, Utah 84150-6330

January 12, 2000

Mr. D. Wayne Headberg
Permits Supervisor
Minerals Reclamation Program
Division of Oil, Gas and Mining
Department of Natural Resources
State of Utah
1594 West North Temple St., Suite 1210
SLC, Utah 84114-5801



Re: **S/035/017: Little Cottonwood Granite Extraction Project - LDS Church
2000 Annual Report of Mining Operations (Form MR-AR)**

In response to your Request for Annual Report for Year 2000, please find the following enclosed:

- 2000 Annual Report of Mining Operations (Form MR-AR) dated January 12, 2001.
- Copy of final field report from Anderson Engineering Company, Inc.
- Copy of final field report from Applied Geotechnical Engineering Consultants, Inc.

We trust that this will satisfy your request and the requirement for our final annual report. We have now completed work at the site. We will monitor re-vegetation conditions in the Spring. We expect to remove all protective fencing and signs as conditions permit.

We appreciate your interest in and support of the project. Thank you.

My Best,



Kerry B. Nielsen, A.I.A.
Project Architect

KBN/kbn.

Sent Via Facsimile: 801.359.3940

attachments: as listed above

c: Tom Hanson, LDS
Gary Holland, LDS
Steve Anderson, Anderson Engineering
Jim Nordquist, AGECE
Jim Peterson, Legacy
David Wahlquist, K&M
File A-1 • 2

dogmwh003.wpd S-035-017 2000 annual report.wpd



State of Utah


DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MININGMichael O. Leavitt
GovernorKathleen Clarke
Executive DirectorLowell P. Braxton
Division Director1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

RECEIVED

JAN 11 2001

SPECIAL PROJECTS
DIVISION

12/19/2000

CORP OF THE PRESIDING BISHOP
15 E NORTH TEMPLE ST
SALT LAKE CITY UT 84111

Re: Request for Annual Report for the Year 2000.

Dear Sirs:

The enclosed report form(s) for the Mine(s) referenced below need to be completed and returned to this office by January 31, 2001.

Mine Status	Mine Number	Mine Name	Contact Person
ACTIVE	S350017	LITTLE COTTONWOOD GRANITE	KERRY NIELSEN

Annual reports are required by Rules R647-3-116 and R647-4-121 of the Division's Amended and New Rules, Minerals Reclamation Program.

Reports are required regardless of annual mine activity, unless you have received a written waiver or formal release from reclamation obligations from the Division.

Thank you for your cooperation and prompt attention to this matter.

Sincerely,

D. Wayne Hedberg
Permit Supervisor
Minerals Reclamation Program